

## Savina Technical Service Bulletin # 5

**Re:** New software version 1.12 and new Operating Instructions

**Date:** March 15, 2002

**Reference Doc:** Immediate report SM 10000000807

**Reason:** Draeger Medical AG & Co. KGaA has released software version 1.12 to improve O<sub>2</sub> control and to adapt new type of microprocessors used on the Controller PCB as of February 2002. New microprocessors labeled on the third line on the processor housing with a code "GA" instead of "BB" require software version 1.12 or higher.

**Devices affected:** The software update with software version 1.12 is mandatory for all Savina units in the USA and Canada with installed software version 1.11 or older.

**When:** By end of September 30, 2002

**Reporting:** To Dräger Medical, Inc. by Fax 1-215-721-5789. A Feedback Form is included in the conversion description.

**Additional Info :** Replace all US Operating Instructions P/N 9037222 1<sup>st</sup> and 2<sup>nd</sup> edition with the new 3<sup>rd</sup> edition included in the SW 1.12 kit.

**Cost:** Free of charge

**Ordering Info:** SW 1.12 Kit Savina P/N 84 14 660

**Distribution:** DrägerService Personnel and authorized Service Organizations for CCS products.

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-721-5789.

Dräger Medical, Inc.  
Technical Product Manager